APPENDIX B Urban Road Safety Audit Photographs



Photograph B1 Poor traffic island conspicuity due to the lack of appropriate warning signs.




Photograph B2 Over abundance of advertising signs distracts drivers from road signs.




Photograph B3 Lack of appropriate parking width, however, there are no yellow no stopping lines restricting vehicles from parking at the kerbside.



Photograph B4 Abrupt termination of an edge line at the end of a section of road which has been recently marked with a flush median / edge line treatment.




Photograph B5 Unnecessary section of guardrail which creates more of a safety hazard than the area of grass if is mounted in front of. Should be replaced with a sightrail.



Photograph B6 Small roundabout with no delineation provided by way of warning signs.



Photograph B7 Use of single curve indicator boards to provide delineation of a smaller roundabout.



Photograph B8 The traffic signals at the intersection in the back ground (by the cars) are hidden from approaching drivers by vegetation.

